


TERNZ
TRANSPORT RESEARCH



 **NZ TRANSPORT AGENCY**
WAKA KOTAHU

**DO 'SAFE-HIT' POST MEDIANS HAVE A PLACE IN
NEW ZEALAND'S SAFE ROADS SYSTEM?**

**Hamish Mackie (TERNZ)
Fabian Marsh (ex NZTA)
Mike Pilgrim (NZTA)**



Rationale for 'safe hit' post median treatment

Hopefully an improved level of safety compared with double yellow audio tactile lines

Cheaper road safety option that might be installed in advance of wire or solid barriers

Median safety continuum?

| | |
|------------------|---|
| Less safe | <p>Painted yellow lines: Standard median configuration traditionally used in New Zealand.</p> <p>ATP on (or next to) painted yellow lines: ATP helps to prevent inadvertent lane departures when driver is in control of vehicle but not deliberate departures, or those where the driver is not in control of their vehicle.</p> <p>Flush median (of varying width) with ATP on right-hand edge lines: In addition to above, the separation provided by the flush median (along with two distinguishable ATP lines) gives added safety via recovery space for deliberate or 'loss of control' departures.</p> <p>Flush median with ATP on right-hand edge lines plus safe-hit posts (i.e. Peka Peka): In addition to above, the safe-hit posts prevent deliberate central median crossing via a perception of damaged property when hit. The perceptual effects of the safe-hit posts alone are unknown.</p> |
| More safe | <p>Wire rope / solid barrier: In addition to above, the barrier physically prevents central median crossing, providing an inherently safe system for head on/cross centreline crashes.</p> |

Purpose of the study

Will take time to get actual safety effects, so...

Understand driver behaviour and perceptions

Maintenance issues

Long-term understanding of benefits and costs



Method



- No pre/post evaluation possible
- 4 treatment plus 5 untreated sites, matched as much as possible with geometry, curve direction etc
- Measures of effectiveness (MOEs):
 - Baseline crash history for future analysis
 - Maintenance issues and costs
 - Speed
 - Lane position
 - Merging
 - Turning
 - Motorist perceptions
 - Other matters of interest (e.g. ATP noise)



Treated site



Untreated site

Results - Crashes

| Crash Date | Crash ID | Dist from side road | Nth/S | Side Road | Mvmt Code | Mvmt description | F | S | M |
|------------|----------|---------------------|-------|--------------|-----------|-------------------------|---|---|---|
| 2000 | 2010056 | 750 | N | Greenhill Rd | CB | loss cntrl left strght | 1 | 3 | 0 |
| 2000 | 2012763 | 400 | S | Peka Peka Rd | DB | loss cntrl left curve | 0 | 0 | 1 |
| 2001 | 2110011 | 300 | N | Greenhill Rd | BA | Head on straight | 1 | 2 | 1 |
| 2002 | 2211278 | 900 | S | Peka Peka Rd | PA | Pedestrian | 0 | 1 | 0 |
| 2004 | 2412023 | 2000 | N | Hemi St | JA | Veh turning | 0 | 1 | 0 |
| 2004 | 2412981 | 1500 | S | Peka Peka Rd | CB | loss cntrl left strght | 0 | 0 | 1 |
| 2005 | 2512116 | 1100 | N | Greenhill Rd | BF | loss cntrl on curve | 0 | 0 | 1 |
| 2005 | 2512936 | 1360 | S | Peka Peka Rd | DA | loss cntrl turn right | 0 | 0 | 1 |
| 2007 | 2711090 | 1500 | S | Peka Peka Rd | AA | pull out to right | 0 | 1 | 2 |
| 2007 | 2711708 | 1170 | S | Peka Peka Rd | CA | strght out of cntrl | 0 | 0 | 1 |
| 2007 | 2712303 | 300 | N | Greenhill Rd | FD | Queue | 0 | 0 | 1 |
| 2007 | 2712827 | 2000 | S | Peka Peka Rd | CB | loss cntrl left strght | 0 | 1 | 3 |
| 2008 | 2812201 | 820 | N | Greenhill Rd | CC | loss cntrl right strght | 0 | 0 | 1 |
| 2008 | 2812552 | 1380 | S | Peka Peka Rd | DB | loss cntrl left curve | 0 | 0 | 1 |
| 2008 | 2812915 | 3000 | N | Ngalo Rd | FD | Queue | 0 | 0 | 1 |
| 2008 | 2813598 | 450 | N | Greenhill Rd | QF | Fell inside veh | 0 | 0 | 1 |
| 2008 | 2813889 | 1280 | S | Peka Peka Rd | CB | loss cntrl left strght | 0 | 0 | 1 |
| 2009 | 2913339 | 400 | N | Greenhill Rd | CB | loss cntrl left strght | 0 | 0 | 1 |

Key Point: This site has a significant crash history

Results - Maintenance

Reported maintenance issues for six months following installation

| Month | Location | Description |
|-----------|--|--|
| April | 0 | |
| May | 0 | |
| June | Sthbnd, North end of barrier on straight | Damage identified during routine inspection. Two duraposts knocked down. Posts and sockets OK. Duraposts bolted back in |
| July | 0 | |
| August | 0 | |
| September | Sthbnd, North end of barrier on straight | Damage identified on routine inspection. Two duraposts damaged. Duraposts will need to be replaced as too damaged to re-install. RG17 at this location also replaced |

Key Point: Overall relatively modest maintenance issues, but need to check in a bit more detail

Results - Speed

Summary of speed measurements for different conditions

| Lane type | treatment | Mean Speed (km/hr) | 85% Speed (km/hr) |
|-----------------------|-----------|--------------------|-------------------|
| Slow and single lanes | Treated | 94 | 101 |
| | Untreated | 95 | 102 |
| Fast lanes | Treated | 103 | 110 |
| | Untreated | 105 | 113 |

Note all differences between treated and untreated sites statistically significant (unpaired t-test, $p < 0.01$)

Key Point: Definitely no higher speed at treated site, possibly slightly lower. Need to consider other route factors at each location though





Results - Lane position


Summary of lane position at treated vs untreated sites

| Lane type | Treatment | Count | Dist to Centreline /RH edge line (m) |
|---------------------------------------|-----------|-------|--------------------------------------|
| Straight single lanes | Treated | 359 | 1.11 |
| | Untreated | 371 | 0.84 |
| Straight Fast lanes (no passing only) | Treated | 66 | 0.78 |
| | Untreated | 81 | 0.72 |

Note all differences between treated and untreated sites statistically significant (unpaired t-test, $p < 0.01$)

Key Point: Vehicles travelled further from RH line at treated sites. Lane departures rare at all sites possibly due to ATP





Results – Motorist Perceptions

Other themes from respondent's open comments were:


- No physical barrier (9 respondents)
- Generally positive statement (7)
- Turning issues (6), this seemed to be related to merging issues (3) as they are at similar locations.
- Noisy rumble strips (6). This theme seems to be related to respondents who live near the merge (southbound) and left-hand curve (northbound) areas.

Key Point: Generally positive feedback from perceptions survey

Discussion




Key points:

- Overall, safe hit post median treatment performed well within the constraints of this trial
- Still need to understand more about safety and maintenance
- DO 'SAFE-HIT' POST MEDIANS HAVE A PLACE IN NEW ZEALAND'S SAFE ROADS SYSTEM? → *Depends on strategic approach*



Discussion

Possible NZTA approach:

| Vehicles per day | Median Treatment |
|--|---|
| Less than 8000 vehicles per day (VPD) → rumble lines |  |
| 8-15,000 VPD → wide central medians (with ATP) |  |
| Greater than 15,000 VPD → median wire rope barrier |  |

